



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 71	WOODSTOCK ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s-between 69-71 (same as felled tree)	434414.76	384918.29	Corylus colurna	434415.64	384917.96
o/s 67	WOODSTOCK ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 65-67 (same as felled tree)	434425.01	384917.35	Liquidambar styraciflua 'Worpl	434427.36	384916.91
o/s 48	WOODSTOCK ROAD	Acer pseudoplatanus	Structural Integrity	Dangerous	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 48 (same as felled tree)	434501.2	384916.59	Liquidambar styraciflua 'Worpl	434501.85	384916.34
o/s 62	WOODSTOCK ROAD	Acer pseudoplatanus	Structural Integrity	Dangerous	TR: Replanting, Corylus colurna - Plant in new 800mm pit at junct Woodstock and emily rd, o/s 62 (same as felled tree)	434457.22	384921.76	Corylus colurna	434456.84	384922.1
o/s 79	WOODSTOCK ROAD	Platanus x hispanica	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 77-79 (same as felled tree)	434393.4	384921.25	Liquidambar styraciflua 'Worpl	434394.99	384920.81
o/s 63	WOODSTOCK ROAD	Tilia x europea	Senescent	Dying	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s-between 61-63 (same as felled tree)	434436.88	384915.91	Corylus colurna	434439.61	384915.45
o/s 66	WOODSTOCK ROAD	Tilia x europea	Structural Integrity	Dangerous	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 64-66 (same as felled tree)	434444.42	384923.63	Liquidambar styraciflua 'Worpl	434446.91	384922.94
o/s 59	WOODSTOCK ROAD	Fraxinus excelsior	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit centrally o/s 57-59 (same as felled tree)	434447.9	384914.56	Liquidambar styraciflua 'Worpl	434450.56	384913.83
o/s 56	WOODSTOCK ROAD	Fraxinus excelsior	Structural Integrity	Dangerous	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 56-58	434482.81	384918.88	Liquidambar styraciflua 'Worpl	434480.81	384918.93

Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 52	WOODSTOCK ROAD	Acer pseudoplatanus	Structural Integrity	Dangerous	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 52 (same as felled tree)	434492.73	384917.86	Corylus colurna	434492.59	384917.79
o/s 40	WOODSTOCK ROAD	Fraxinus excelsior	Structural Integrity	Dangerous	TR: Replanting, Corylus colurna - Plant in new 800mm pit o/s 38-40 (same as felled tree)	434521.12	384914.13	Corylus colurna	434523.06	384913.81
o/s 30	WOODSTOCK ROAD	Acer pseudoplatanus	Structural Integrity	Dangerous	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 30 (same as felled tree)	434544.68	384911.85	Liquidambar styraciflua 'Worpl	434544.73	384911.66
o/s 11	WOODSTOCK ROAD	Fraxinus excelsior	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800mm pit o/s 11 (same as felled tree)	434577.73	384899.39	Liquidambar styraciflua 'Worpl	434577.6	384899.4
adj church	WOODSTOCK ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Corylus colurna - Plant in new 800mm pit at end of rd/junction Empire rd (at side of Church)	434605.95	384895.91	Corylus colurna	434605.9	384895.92